Hertfordshire County Scout Council Phasels Wood Activity Centre Building Risk Assessment



| 1 | Activity Area Frequency of use | | Brynbach | | |
|---|--|---|-----------------------------|---|--|
| | | | As required | | |
| 2 | | onnel Involved per of people | Instructors/Staff 1 – 36 | | |
| 3 | Poter 1 2 3 4 5 6 | tial Hazards Uneven, wet floors Fire risk Electrical Equipment Working at height Unauthorised access Climbing over stored m | aterials | 4 | Risk Level Medium Low Low Low Medium Medium |

5 Measures Taken to Control Hazards

- 1 Ensure floor area kept clear, obstructions tidied away, spills cleared and floors allowed to dry after cleaning. Ensure external areas at risk are well lit at night.
- 2 Ensure combustible material cleared regularly, fire extinguishers in place and sources of ignition controlled
- 3 Use as per manufacturers instructions, PAT regime in place, minimise trailing cables, do not overload fuses, appropriate trips on circuits.
- 4 Use access equipment appropriate to job and for which training has been given
- 5 Provide appropriate signage and lock when not in use.
- 6 When removing stored materials, ensure that they are removed in a methodical way without climbing over other items.

| Compilation date - Review period - Reference Number - | SEPT 2022 12 Months PW/B014 | Compiled by :- DS Reviewed by – MB Reviewed Date: 01.10.23 | |
|---|-----------------------------------|--|--|
| Reference Number - | PW/B014 | Reviewed Date: 01.10.23 | |